

FIG. I

2/30




FIG. 2

3/30




FIG. 4

4/30




FIG. 7




FIG. 5




FIG. 6




FIG. 8

5/30




FIG. 9

SUBSTITUTE SHEET (RULE 26)

6/30







FIG. 10



8/30



9/30



10/30




FIG. 17




FIG. 18

11/30




FIG. 19

12/30




FIG. 22




FIG. 21




FIG. 20

13/30




FIG. 23




FIG. 24

14/30




FIG. 25

15/30




FIG. 26




FIG. 27

16/30




FIG. 28




FIG. 31




FIG. 30




FIG. 29

80

The diagram shows a coiled spring with a label '80' pointing to the top left. The spring is wound in a clockwise direction, with the label positioned above the topmost coil.

18/30




FIG. 33




FIG. 32

19/30

FIG. 34







FIG. 35






21/30



22/30



23/30






FIG. 42

24/30



25/30




FIG. 45

26/30




FIG. 46

27/30




FIG. 46A

28/30




FIG. 47

29/30




FIG. 49




FIG. 48

30/30




FIG. 51




FIG. 50